



OKLAHOMA DRINKING WATER

# LEAD TESTING

IN PUBLIC SCHOOLS & CHILD CARE FACILITIES

## Hydro-Eakly Es Initial Sampling Results

Samples outlined in this report were collected under the Oklahoma Lead in Schools and Child Care Program (LWSC) on 07/15/2026 from 407 East Seventh Street, Hydro, OK 73048.

See below for an overview of the outlet descriptions noted in the results report:

Outlet Type Code Key:

CF: Classroom Faucet

KF: Kitchen Faucet

BF: Bathroom Faucet

NS: Nurse Office Sink

RA: Refrigerator Appliance

OF: Outdoor Faucet

IM: Ice Machine

DW: Drinking Water Fountain

WC: Water Cooler With Chiller Unit

Water Cooler Definition: A machine that is connected to the building's water supply for a continuous supply of water and to electricity to run a refrigeration unit to cool the incoming water.

Drinking Fountain Definition: A machine that is connected to the building's water supply for a continuous supply of water.

| #  | Outlet ID | Building # | Floor # | Room # / Name                           | Outlet Type Code | Water Cooler Make and Model | Comments                | Initial First Draw Result Final (ppb) | Initial Flush Draw Result Final (ppb) | Initial Sample Date(s) | Action Needed?          | Remediation Action Taken |
|----|-----------|------------|---------|-----------------------------------------|------------------|-----------------------------|-------------------------|---------------------------------------|---------------------------------------|------------------------|-------------------------|--------------------------|
| 1  | 3283-13   | 3          | 1       | Training room                           | CF               |                             |                         | 3.33 ppb                              | <1 ppb                                | 07/15/2026 08:30       | Remediation Recommended |                          |
| 2  | 3283-14   | 3          | 1       | Event building concessions              | CF               |                             |                         | 3.16 ppb                              | <1 ppb                                | 07/15/2026 08:30       | Remediation Recommended |                          |
| 3  | 3283-2    | 1          | 1       | Kitchen                                 | KF               |                             | 3 bay sink, left faucet | 1.76 ppb                              | <1 ppb                                | 07/15/2026 08:30       | Remediation Recommended |                          |
| 4  | 3283-1    | 1          | 1       | Kitchen                                 | KF               |                             | 2 bay sink              | 1.21 ppb                              | <1 ppb                                | 07/15/2026 08:30       | Remediation Recommended |                          |
| 5  | 3283-5    | 2          | 1       | High school hallway                     | WC               | Elkay EZH20                 | Far left fountain       | <1 ppb                                | <1 ppb                                | 07/15/2026 08:30       | No Further Action       |                          |
| 6  | 3283-4    | 2          | 1       | High school hallway                     | WC               | Elkay EZH20                 | Bottle filler           | <1 ppb                                | <1 ppb                                | 07/15/2026 08:30       | No Further Action       |                          |
| 7  | 3283-3    | 1          | 1       | Kitchen                                 | IM               | Manitowac                   |                         | <1 ppb                                |                                       | 07/15/2026 08:30       | No Further Action       |                          |
| 8  | 3283-8    | 2          | 1       | High school front lobby, right fountain | WC               | Elkay                       |                         | <1 ppb                                | <1 ppb                                | 07/15/2026 08:30       | No Further Action       |                          |
| 9  | 3283-6    | 2          | 1       | High school front lobby                 | WC               | Elkay EZH20                 | Bottle filler           | <1 ppb                                | <1 ppb                                | 07/15/2026 08:30       | No Further Action       |                          |
| 10 | 3283-9    | 3          | 1       | Event building lobby, left fountain     | WC               | Elkay                       |                         | <1 ppb                                | <1 ppb                                | 07/15/2026 08:30       | No Further Action       |                          |
| 11 | 3283-7    | 2          | 1       | High school front lobby, left fountain  | WC               | Elkay EZH20                 |                         | <1 ppb                                | <1 ppb                                | 07/15/2026 08:30       | No Further Action       |                          |
| 12 | 3283-10   | 3          | 1       | Event building lobby, bottle filler     | WC               | Elkay EZH20                 | Red filter status       | <1 ppb                                | <1 ppb                                | 07/15/2026 08:30       | No Further Action       |                          |
| 13 | 3283-11   | 3          | 1       | Event building lobby, right fountain    | WC               | Elkay EZH20                 |                         | <1 ppb                                | <1 ppb                                | 07/15/2026 08:30       | No Further Action       |                          |

[illegible]