



OKLAHOMA DRINKING WATER

# LEAD TESTING

IN PUBLIC SCHOOLS & CHILD CARE FACILITIES

District: Lindsey Asher Partnerships

School: Advance Start Learning Center

Sampling Dates: 4/14/2025, 4/17/2026

Status: Completed Sampling

## RESULTS

Below are the results from the first and second rounds of testing of drinking water for lead that was conducted at Lindsey Asher Partnerships – Advance Start Learning Center. The initial sampling event occurred on April 14, 2025. The resampling event occurred on April 17, 2026.

In the initial sampling, thirteen (13) outlets were tested resulting in a total of twenty-six (26) samples being sent to the lab.

- Fifteen (15) samples had no detectable level of lead.
- Eleven (11) samples had a low detection of lead between 1.0 and 14.9 micrograms per Liter (ug/L).
- Zero (0) samples had a high detection of lead equal to or above 15.0 micrograms per Liter (ug/L).

In the resampling, two (2) outlets were tested resulting in a total of four (4) samples being sent to the lab.

- Zero (0) samples had no detectable level of lead.
- Four (4) samples had a low detection of lead between 1.0 and 14.9 µg/L.
- Zero (0) samples had a high detection of lead equal to or above 15.0 µg/L.

The table below shows all sample results. Sample results are in micrograms per liter, shown as µg/L. For more information on how to read this report, please see our **Results Interpretation Fact Sheet**.

Sample ID	Outlet Description	First Draw (µg/L)	Flush (µg/L)	Remedial Action	First Draw (µg/L)	Flush (µg/L)
		Initial Sampling			Resampling	
<b>Non-Detect (&lt;1.0 µg/L)</b>						
1-1-LOB-WC1	Water cooler in lobby; left side	<1.0	<1.0	N/A		
1-1-LOB-WC2	Water cooler in lobby; right side	<1.0	<1.0	N/A		
1-1-KB-BF1	Bathroom faucet in kids' bathroom; far left side	<1.0	<1.0	N/A		
1-1-KB-BF2	Bathroom faucet in kids' bathroom; left center unit	<1.0	<1.0	N/A		
1-1-IR-CF1	Classroom faucet in infant room	<1.0	<1.0	N/A		
<b>Low Detection (1.0 - 14.9 µg/L)</b>						
1-1-KIT-KF2	Kitchen faucet in facility kitchen; left of burners	1.1	<1.0			

Sample ID	Outlet Description	First Draw (µg/L)	Flush (µg/L)	Remedial Action	First Draw (µg/L)	Flush (µg/L)
		Initial Sampling			Resampling	
1-1-KB-BF4	Bathroom faucet in kids' bathroom; far right side	1.2	1.1			
1-1-KB-BF3	Bathroom faucet in kids' bathroom; right center unit	<1.0	1.4			
1-1-LOB-CF1	Classroom faucet in lobby	1.7	<1.0			
1-1-KIT-KF1	Kitchen faucet in facility kitchen; traditional sink	1.7	1.4			
1-1-SR-BF1	Bathroom faucet in staff restroom	1.8	<1.0			
1-1-2Y-CF1	Classroom faucet in 2-year old room	5.4	<1.0		1.8	1.2
1-1-1Y-CF1	Classroom faucet in 1-year old room	11.7	1.3		1.9	2.3