

2019 ODOT Standard Specifications for Highway Construction Errata

Section Number	Description of Errata	Date Posted
307.01	Section 307, SUBGRADE TREATMENT Remove the second paragraph from subsection 307.01.B and add it as the second paragraph to subsection 307.01 DESCRIPTION. This information applies to both subsection 307.01.A and 307.01.B.	6-26-25
317.02	Subsection 317.02 MATERIALS Revise the subsection number for the material reference <i>Geotextile for Bond Breaker</i> from 712.1 to 712.10 .	6-26-25
411.03	Subsection 411.03.F, Material Transfer Vehicle After the first paragraph, add the following sentence: “Unless otherwise specified in the Contract, provide an MTV to place the top two lifts of hot mix asphalt (HMA) for pavements designed for a minimum of 10 million ESALs.”	6-26-25
411.03	Subsection 411.03.G, Compactor After the first sentence, add the following sentence: “Pneumatic tired compactors are not required for Stone Matrix Asphalt (SMA) mixes.”	3-3-25
411.04	Subsection 411.04.K(1), Compaction In subsection (1) General, end of the second paragraph, add the following sentence: “Pneumatic tired rollers are not required for SMA mixes.”	3-3-25
411.04	Subsection 411.04.K(2)(a), Layer at Least 1½ in (38 mm) Thick Move the following sentence in this subsection after the second paragraph (<i>before Table 411:2</i>): “The Department will base acceptance and pay adjustments on Department-approved tests in accordance with the following schedule:”	6-26-25
411.04	Subsection 411.04.N(2)(b), Table 411:4, “Acceptable Schedule” Revise the pay factor equation for the average of deviations from target (<i>without regard to sign</i>) from $-0.16X + 0.24X + 1.00$ to “$-0.16X^2 + 0.24X + 1.00$” Special Provision 411-025(a)19 was created to address this and is added to the proposal when HMA/WMA pay items are utilized.	3-3-25
411.05	Subsection 411.05, METHOD OF MEASUREMENT Delete the second sentence: “The Resident Engineer will measure bituminous material by the gallon [liter] or ton [metric ton].”	6-26-25
414.02	Subsection 414.02, MATERIALS Revise the subsection number for the material reference <i>Steel Reinforcement, Dowel Bars & Tie Bars</i> from 702.03 to 723 .	6-26-25
503.04	Subsection 503.04.H, Tolerances First paragraph, revise the first sentence by deleting the reference to Table 503:4 as follows: “Correct the production process if member dimensions approach a tolerance limit specified in Table 503:1, Table 503:2, and Table 503:3.”	6-26-25

2019 ODOT Standard Specifications for Highway Construction Errata

503.04	Subsection 503.04.I, Corrective Actions Third bullet point, revise the reference for subsection 105.3 to 105.03 .	6-26-25
505.02	Subsection 505.02, MATERIALS Revise the subsection number for the material reference <i>Early Strength Concrete for Bridge Deck Patching and Overlays</i> from 701.2 to 701.20 .	6-26-25
505.03	Subsection 505.03.E, Hand-Held Blast Cleaning Equipment Revise the quantity from 4,000 psi [28 Mpa] to “7,000 psi [48 Mpa]”	3-3-25
505.04	Subsection 505.04.C(2)(e), Surface Wetting for Latex Modified Concrete or Early Strength Concrete Second sentence, revise the time from 1 hr to “4 hr” After the last sentence, add the following sentence: “Protect cleaned surface with polyethylene film and roll polyethylene film as the latex is being placed.”	3-3-25
505.04	Subsection 505.04.E(3)(f), Evaporation Control and Curing Revise the reference to read 504.04.D(5), “Fogging and Curing Requirements”	3-3-25
508.04	Subsection 508.04.G, Extension of Existing Cast-in-Place Culvert Revise the first sentence to read: “Perform work to extend an existing cast-in-place culvert, when required by the contract documents, as follows:”	6-26-25
510.04	Subsection 510.04.E(2)(b), Soil Reinforcement Third paragraph, revise the reference for subsection 723.03 to subsection 723.02 .	6-26-25
513.02	Subsection 513.02, MATERIALS Revise the subsection number for the material reference <i>Early Strength Concrete (ESC) for Bridge Deck Patching and Overlays</i> from 701.2 to 701.20 .	6-26-25
513.03	Subsection 513.03.F, Lighting Equipment Revise the reference from Subsection 509.4.C(3)(c) to 509.04.C(3)(c) .	6-26-25
517.02	Subsection 517.02.H, Mechanical Couplers and Heat Shrink Sleeve Requirements Move Table 517:2, “Heat Shrink Sleeve Specifications” from Subsection 517.02.I to 517.02.H, after the second paragraph.	6-26-25
535.04	Subsection 535.04.F, Acceptance Delete the words “for bridge decks” from the sentence.	3-3-25
535.04	Subsection 535.04.F, Acceptance Revise the reference to read 515.04.D, “Acceptance”	3-3-25
601.01	Subsection 601.01, DESCRIPTION Bullet list, delete bullet two “Type I-A Plain with Filter Blanket” and replace with “Type I Plain with Filter Blanket.” Bullet list, delete bullet four “Type II-A Special Plain with Filter Blanket” and replace with “Type II Special Plain with Filter Blanket.”	6-26-25

2019 ODOT Standard Specifications for Highway Construction Errata		
610.04	Subsection 610.04.A(4), Curing After the last sentence, add the following sentence: “The timely application of an impervious membrane curing compound is acceptable in accordance with Subsection 414.04.J(2), “Impervious Membrane.”	3-3-25
611.04	Subsection 611.04.H, Precast Units Last paragraph, revise the reference from Subsection 613.04.E, “Outlet Lateral Headwalls” to Subsection 613.04.H, “Joining Pipe Conduit.”	6-26-25
622.02	Subsection 622.02, MATERIALS Replace the second paragraph with the following: “Provide two coats of 93% pure zinc paint and overcoat with a polyurethane-base paint for outdoor use.”	6-26-25
623.06	Subsection 623.06, BASIS OF PAYMENT Pay item list, revise the pay item “(H) BLOCKOUTS” to “(H) GUARDRAIL BLOCKOUT REPLACEMENT.”	6-26-25
629.06	Subsection 629.06, BASIS OF PAYMENT Add the following to the pay item list “(E) MAILBOX..... Each”	3-3-25
733.04	Subsection 733.04, NONMETALLIC WATERLINE PIPE AND FITTINGS Revise the material reference list to include the following ASTM Specifications: Acrylonitrile Butadiene-Styrene (ABS) - D1527 ; Polyethylene (PE) - D2104 ; Polybutlene (PE) - D2662 .	6-26-25